


Machine Upgrades

Powerpack Motor Upgrade with Bearing Temperature Monitoring

Flender powerpack motors are no longer available. GE motors have long lead times and high replacement costs.



Contact Husky for enquiry:

Asia Pacific: apafms@husky.ca
North & South America: lscamer@husky.ca
Europe & Africa: afmaemea@husky.ca

Category

- Performance & Productivity Improvements
- Reduced Energy
- **Improved Maintainability**
- Obsolescence Management

Upgrade Benefits

Husky recommends ordering this upgrade pro-actively to minimize system downtime resulting from the failure of the existing obsolete motor.

Ordering the replacement upon failure will result in significant machine downtime.

FLENDER Motors:
Affected machines can be upgraded with Emod motors. Bearing temperature monitoring is standard with Encore™

GE Motors:
Machines built with GE motors can still be replaced with existing inventory, however because of cost and lead time, upgrades to Emod (with standard bearing temperature monitoring) are recommended.

Installation Instructions

Please refer to quotation (approximately 2-4 days)

Lead time ~ 14 weeks

To request a quotation for the IPC Upgrade, contact your local CSM (Customer Success Management) Business Manager or send an inquiry to your local CSM Sales Contact listed below.

Product Line Affected

- G-Line PET
- G-Line General Purpose
- G-Line Packaging
- Index PET